


Specimen ID: UCB-PN1  
 Keywords: Pre-Northridge, simulated field welding, column flange fracture, continuity plate yielding, small rotation capacity  
 Test Location: University of California, Berkeley  
 Test Date: February 9, 1995  
 Principal Investigator: Egor P. Popov; with Marcial Blondet, Lev Stepanov, and B. Stojadinovic  
 Related Summaries: 24  
 Reference: "Experimental Investigations of Beam-Column Subassemblages", *Report No. SAC 96-01*, March 1996.  
 Funding Source: FEMA / SAC Joint Venture, Phase I

**CONNECTION DETAIL**



**MATERIAL PROPERTIES AND SPECIMEN DETAILS**

Member	Size	Grade	Yield Stress (ksi)		Ultimate Strength (ksi)	
			mill certs.	coupon tests *	mill certs.	coupon tests *
Beam	W36x150	A572 Gr. 50	62.6	60.6 flange 60.1 web	74.7	68.8 flange 69.7 web
Column	W14x257	A572 Gr. 50	53.5	48.3 flange NA web	72.5	67.8 flange 76.1 web
Welding Procedure Specification	All welds FCAW-SS in conformance with AWS D1.1-94, performed with 0.120" diameter AWS E70T-4 electrodes. Preheat and interpass temperature per Table 4.3. Fillet weld of shear tab to beam web performed with 0.072" diameter AWS E71T-8 electrode.					
Shear tab	5/8"x30"x4" plate with ten 7/8" A325 bolts					
Panel zone	No doubler plates					
Continuity plates	1/2" plates with c.p. weld					
Boundary conditions	Single-sided test, no floor slab, axial load in lower half of column equal to shear in beam, specimen tested in flat position					
Other detailing	5/16" fillet weld upper and lower ends of shear tab					


N.A. = not available

\*Coupon locations per ASTM

## BACKGROUND

The objectives of testing the Pre-Northridge specimens were to replicate in the laboratory the failure modes observed in the field after the Northridge earthquake to develop a better understanding of the failure mechanisms, and to acquire data on the likely deformation characteristics of beam-column connections constructed to industry standards before 1994. The specimen described in this summary was fabricated under controlled conditions by a local commercial steel fabricator to details specified by SAC and the principal investigator. It was intended to be identical to the specimens described in Test Summaries No. 11 and 12. However, Grade 50 beam steel was used in this specimen and Specimen UCB-PN2, instead of the A36 steel which was originally specified. The beam in Specimen UCB-PN3 was fabricated from A36 material. This specimen was also of the same size as the specimens described in Test Summaries No. 7, 8, and 9 that were tested at the University of Texas at Austin. Because each of these were fabricated under controlled conditions, however, it is possible that their quality is superior to typical moment connections fabricated in the field prior to the Northridge earthquake. As such, some field-fabricated moment connections may exhibit less rotation capacity than these test specimens.

The standard SAC/ATC-24 loading history was used in the testing, and the testing was performed quasi-statically. The reference loading displacement ( $\delta_y$ ) for the specimen was specified as 1.00 in.



## DISPLACEMENT HISTORY AND KEY EXPERIMENTAL OBSERVATIONS

Applied Displacement History	Key Observations of the Test	
<p style="text-align: center;"><math>\delta_y = 1.0</math> in. (analytical)</p> <p style="text-align: center;">displacement</p> <p style="text-align: center;">3<math>\delta_y</math> 2<math>\delta_y</math> <math>\delta_y</math> -<math>\delta_y</math> -2<math>\delta_y</math> -3<math>\delta_y</math></p>	Point	Description
	1	Yielding of beam top and bottom flanges
	2	Yielding of the back column flange at the continuity plate level
	3	Yielding in the middle of panel zone, slight bolt movement in the shear tab
	4	Fracture of the column flange adjacent to the beam bottom flange through its entire width

## DETAILED TEST RESULTS

Quantity (see Introduction for definitions used in UCB tests)		Maxima
Force/Displacement Properties	Peak actuator force (kips):	223
	Beam deformation (in.) total/beam only:	2.57/1.22
	Experimental yield displacement (in.)	0.90
Rotation Capacity	Maximum plastic rotation (% radian) total/beam only:	0.88/0.33
	Cumulative plastic rotation (% radian):	NA
Energy Dissipation Properties	Cumulative energy dissipated (k-in.):	1680

Mode of failure: Fracture of the column flange during the second positive excursion to  $3\delta_y$  cycle.

## DISCUSSION

Specimen 10 behaved elastically up to and including the cycles to  $1\delta_y$ . The specimen yielded during the first excursion to  $2\delta_y$ . Yielding was noted on both flanges and on the back column flange at the continuity plate level. Slight yielding was also noted in the panel zone. In addition, slight movement in the shear tab plate due to bolt movement was noted. The specimen failed during the second positive excursion to  $3\delta_y$ . The failure mode was fracture of the column flange through its entire width adjacent to the beam bottom flange. The crack started underneath the backing plate for the beam bottom flange weld. It extended diagonally across the flange to enter the corner of the panel zone. In the panel zone, the crack branched in two directions. One branch extended approximately 8 in. along the continuity plate, and the other branch stretched approximately 10 in. along the column flange. Significant yielding in the column flanges and the lower part of the continuity plate was noted. The maximum plastic rotation of the connection was approximately 0.88% radian, consisting of 0.55% radian from the panel zone, and 0.33% radian from the beam. The failure mode of the specimen with the crack extending throughout the flange width into the column web was observed in several structures after the Northridge earthquake, but this was the first time such a failure had been reproduced in the laboratory. It is likely that the inadvertent overstrength of the beam compared to that assumed in the design (Gr. 50 steel as compared to A36 steel) contributed to this type of failure mechanism.

## DISCLAIMER

This summary has been prepared from the cited reference. The SAC Joint Venture has not verified any of the results presented herein, and no warranty is offered with regard to the results, findings, and recommendations presented, either by the Federal Emergency Management Agency, the SAC Joint Venture, the individual joint venture partners, their directors, members, or employees. These organizations and individuals do not assume any legal liability or responsibility for the accuracy, completeness, or usefulness of any of the information, products, or processes included in this publication. The reader is cautioned to carefully review the material presented herein. More detailed information is available in the cited reference.