


Specimen ID: UCB-RN1
 Keywords: Repaired, beam doubler plate, beam splice plate, column replacement piece, beam and column flange yielding, weld crack, medium rotation capacity
 Test Location: University of California, Berkeley
 Test Date: August 2, 1995
 Principal Investigator: Egor P. Popov; with Marcial Blondet, Lev Stepanov, and B. Stojadinovic
 Related Summaries: 10
 Reference: "Experimental Investigations of Beam-Column Subassemblages", *Report No. SAC 96-01*, March 1996.
 Funding Source: FEMA / SAC Joint Venture, Phase I



MATERIAL PROPERTIES AND SPECIMEN DETAILS

| Member | Size | Grade | Yield Stress (ksi) | | Ultimate Strength (ksi) | |
|---------------------------------|---|-------------|--------------------|-------------------------|-------------------------|-------------------------|
| | | | mill certs. | coupon tests * | mill certs. | coupon tests * |
| Beam | W36x150 | A572 Gr. 50 | 62.6 | 60.6 flange 60.1 web | 74.7 | 68.8 flange 69.7 web |
| Column | W14x257 | A572 Gr. 50 | 53.5 | 48.3 flange NA web | 72.5 | 67.8 flange 76.1 web |
| Beam splice plate | 1 1/4" plate | A36 | N.A. | N.A. | N.A. | N.A. |
| Column splice | W14x257 | A572 Gr. 50 | N.A. | N.A. | N.A. | N.A. |
| Web doubler plate | 3/4" plate | N.A. | N.A. | N.A. | N.A. | N.A. |
| Welding Procedure Specification | Original welds: WPS given in Test Summary No. 10. Repair welds: conforms with AWS D1.1-94 and be capable of delivering a minimum of 20 ft-lbs at 20 F as measured by a Charpy V-Notch impact test; no other details available | | | | | |
| Shear tab | 5/8"x30"x4" plate, weld to beam web, remove bolts; web doubler plate added | | | | | |
| Panel zone | No doubler plate | | | | | |
| Continuity plates | Original 1/2" plates with c.p. weld at top, replace bottom plate with a 3/4" with c.p. weld | | | | | |
| Boundary conditions | Single-sided test, no floor slab, axial load in bottom half of column equal to beam shear, specimen tested in flat position | | | | | |
| Other detailing | No repairs to top flange | | | | | |


N.A. = not available

*Coupon locations per ASTM

BACKGROUND

This was a test of repairs to specimen UCB-PN1 which was originally tested on February 9, 1995. The original specimen failed during the second positive excursion to $3\delta_y$. The failure mode was fracture of the column flange adjacent to the bottom beam flange. The failure initiated underneath the backing plate at the beam bottom flange weld. It extended diagonally across the flange and entered the corner of the panel zone. In the panel zone, the crack branched in two directions. Significant yielding in the column flanges and the lower part of the continuity plate was noted. Minor yielding in the panel zone and the beam flanges was observed. The reference loading displacement (δ_y) for the specimen was specified as 1.00 in.

The repair consisted of removing a section of the beam flange and web, removing the bottom continuity plate, removing a section of the column web and flange, replacing the removed column section with a new W14x257 Gr. 50 piece, welding the column flange and web, adding a beam splice plate to connect the beam bottom flange to the newly placed column piece, welding the existing shear tab to the beam web and removing the existing bolts, welding a new beam web doubler plate to the column flange and the beam web on the opposite side of the shear tab. The standard SAC/ATC-24 loading history was used in the testing, and the re-testing was performed quasi-statically.



DISPLACEMENT HISTORY AND KEY EXPERIMENTAL OBSERVATIONS

| Applied Displacement History | Key Observations of the Test | |
|--|------------------------------|--|
| $\delta_y = 1.0$ in. (original specimen) | Point | Description |
| | 1 | Yielding of the beam top flange, beam bottom splice plate, and back flange of the column at the bottom web stiffener |
| | 2 | Fracture of the beam top flange weld, initiating in the middle and propagating towards the edges. |

DETAILED TEST RESULTS

| Quantity (see Introduction for definitions used in UCB tests) | | Maxima |
|---|--|-----------|
| Force/Displacement Properties | Peak actuator force (kips): | 260 |
| | Beam deformation (in.) total/beam only: | 3.54/1.43 |
| | Experimental yield displacement (in.): | 1.08 |
| Rotation Capacity | Maximum plastic rotation (% radian) total/beam only: | 1.55/0.49 |
| | Cumulative plastic rotation (% radian): | N.A. |
| Energy Dissipation Properties | Cumulative energy dissipated (k-in.): | 4440 |

Mode of failure: Fracture of the beam top flange weld during the first negative $4\delta_y$ cycle.

DISCUSSION

Specimen UCB-RN1 behaved elastically up to and including the $1\delta_y$ cycles. The specimen sustained three displacement cycles at $2\delta_y$, and three displacement cycles at $3\delta_y$ with some yielding of the beam top flange, the beam bottom splice plate, and the back flange of the column at the lower continuity plate level. The measured beam flange strains significantly exceeded the yield value. Strain gages also indicated yielding in the panel zone. The specimen failed during the first negative excursion to $4\delta_y$. A fracture initiated at the middle of the beam top flange and propagated to the flange edges. Due to unloading, the crack stopped 1 in. short of the edges of the beam flange. The maximum plastic rotation of the connection was approximately 1.50% radian.

DISCLAIMER

This summary has been prepared from the cited reference. The SAC Joint Venture has not verified any of the results presented herein, and no warranty is offered with regard to the results, findings, and recommendations presented, either by the Federal Emergency Management Agency, the SAC Joint Venture, the individual joint venture partners, their directors, members, or employees. These organizations and individuals do not assume any legal liability or responsibility for the accuracy, completeness, or usefulness of any of the information, products, or processes included in this publication. The reader is cautioned to carefully review the material presented herein. More detailed information is available in the cited reference.